



TIPS AND TRICKS:

Air Conditioning Malfunction

Application:

2015-2018 Audi A3
and S3 2015-2018
VW Golf

In 2014, a technical service bulletin was issued by VW for the Golf and A3 2013 models with the CKFC/CRBC engine due to vehicles suffering from air conditioning failure. This failure can be attributed to refrigerant loss.

If you are having a A/C system malfunction due to low refrigerant loss. There may be not be a manufacturing defect with the Valeo condenser 814375. In order to identify the correct root cause of the issue, it is advised to check the full A/C system for leaks, paying special attention to the **A/C charging valves**.



If through vehicle diagnosis, the root cause of the issue is in fact a refrigerant loss through the A/C charging valves, Valeo recommend performing the following steps:

- Draining the air-conditioning system.
- Renewing the affected air-conditioning charging valves.
- Re-filling the air-conditioning system.
- Check the leak has been fixed.

Please note, if the condenser or other associated A/C components are returned and show no sign of leaking Valeo may reject claim for no defect found.



Please visit us @
valeoservice.us



Technical Assistance
1-888-718-2536
Press option #2 for technical
support

Smart care for you 