

TIPS AND TRICKS:

Why Checks Should Be Made Before Fitting


All applications **Part numbers** All Valeo A/C COMPRESSORS

The Problem

Valeo Service warranty department have been receiving compressors back as 'incorrect for application', which clearly show evidence of installation. A/C system parts are supplied with all pipe connections capped/sealed to prevent moisture from entering the component. If the caps are removed and the part has been attempted to be installed, Valeo Service is unable to return the product to stock.

The Solution


Visual checks of the component and a comparison with the old unit should be made before the product is fitted to ensure compatibility



Check the pulley size the off set and belt type to the original compressor



Compare the electrical connection to the original compressor



Compare the mounting points and fixing brackets match the original compressor



Visually check the positioning of the pipe fitting



Please visit us @ valeoservice.us



Technical Assistance
1-888-718-2536
Press option #2 for technical support

Smart care for you